

Craddle headwall should be remortered.

