


areas of extensive corrosion and scattered perforations







Stone heatwall at inlet should be repaired







Bank erosion at outlet should be repaired.