



Bank erosion at outlet should be repaired.