

Stone heatwall at inlet should be repaired

