











A photograph showing a concrete cradle headwall. On the left, a corrugated metal pipe is visible. The concrete wall has several orange rust stains. The top of the wall is overgrown with green and yellowing vegetation. The bottom of the wall is dark and has some small green plants growing from it.

Minor map cracking in cradle headwall.









Preforations at outlet.









