





















SEAM SEPERATION/ROTATION ALONG FABRIC PAD
AT DOWNSTREAM END AT ABUTMENT 1

