

A photograph showing the underside of a concrete ceiling. A prominent vertical crack runs down the center. Two horizontal concrete beams are visible, one on the left and one on the right, meeting the ceiling. The concrete surface is weathered and shows some staining. A date stamp is located in the bottom right corner.

09/04/2020