

A photograph showing a close-up of a concrete wall. A horizontal metal beam, heavily rusted and brown, is positioned on the left side of the frame. The concrete wall is light-colored with visible vertical and diagonal cracks. There are patches of green moss or algae on the wall, particularly near the top and bottom edges. The overall scene suggests an old or neglected structure.

10/02/2020