

A photograph of a concrete wall, likely part of a bridge or industrial structure. The wall features horizontal rebar reinforcement. A prominent vertical crack runs down the center, and a horizontal crack is visible near the bottom. The surface is weathered, with patches of green moss or algae growth. At the base, there is a rough, uneven area with some debris and a vertical wooden post. The date '08/25/2020' is printed in orange at the bottom right.

08/25/2020