

A photograph showing a concrete ceiling with green-painted steel beams. There is significant rust and peeling paint along the joints between the beams and the ceiling. The concrete surface is cracked and discolored. The date 08/25/2020 is printed in orange at the bottom center.

08/25/2020