

A photograph of a road surface showing a significant longitudinal crack. The crack runs vertically through the center of the frame, starting from the top edge and extending down to the bottom. It crosses two parallel yellow lines that run horizontally across the middle of the image. The road surface is grey asphalt, and the crack reveals a darker, possibly wet or damaged, layer underneath. At the top of the image, a concrete curb is visible. In the bottom left corner, there is some dry grass and debris. A date stamp is located in the bottom right corner.

09/01/2020