

A photograph showing a corner of a structure with a light blue-green metal surface that is severely corroded with brown rust. The rust is most prominent along the edges and in vertical streaks. To the left is a grey concrete wall, and at the bottom is a concrete floor with some debris and a green stain. A date stamp '09/02/2020' is visible in the bottom right.

09/02/2020