

A photograph showing a corner of a structure with significant corrosion. The left wall is made of grey concrete. The right wall is covered in a light blue or green paint that is heavily peeling and flaking, revealing a thick layer of brown rust underneath. The floor is made of concrete and is covered with a pile of debris, including broken pieces of wood, metal, and concrete. A date stamp is visible in the bottom right corner of the image.

09/02/2020