

A photograph showing a concrete ceiling with several visible cracks. Two large, dark, rusted metal beams run diagonally across the frame, one on the left and one on the right. The concrete is a light gray color with some darker, possibly water-stained or moldy, areas. The lighting is somewhat dim, and the overall appearance suggests an older or neglected structure.

09/02/2020