

A photograph showing the corner of a room with significant structural damage. The walls are covered in peeling paint, revealing a greenish-grey underlayer. The ceiling and upper walls show exposed wooden lath and some dark, possibly moldy, areas. The floor is made of concrete and is cracked and stained. A date stamp is visible in the bottom right corner.

09/15/2020