

A photograph of a tunnel interior. On the left, a dark, rusted metal wall is visible. In the center, a vertical metal support structure, possibly a lag bolt or a small column, is attached to a light-colored, textured concrete wall. The support structure shows significant rust. Below it, a horizontal metal beam is also visible, with a bolt or nut protruding from it. The floor of the tunnel is covered in a layer of dirt and debris. The overall lighting is dim, typical of an underground environment.

09/03/2020