



09/02/2020



09/02/2020



09/02/2020



09/02/2020





09/02/2020



09/02/2020

A photograph showing a perspective view of a wooden bridge deck. The bridge is constructed from weathered wooden planks, with a central section of asphalt pavement. The surface is wet, reflecting light, and shows signs of wear and debris. Metal guardrails are visible on both sides of the bridge. The background shows a dirt path leading away from the bridge and some greenery. A date stamp '09/02/2020' is located at the bottom center of the image.

09/02/2020



09/02/2020





09/02/2020



09/02/2020



09/02/2020



09/02/2020



09/02/2020



09/02/2020



09/02/2020





09/02/2020



09/02/2020



09/02/2020



Lifetime Limited Warranty

GENUINE WOLMANIZED Douglas Fir

Quality Monitored by Timber Production A.A.C.C. Inspection

Wood Treated Right™ BELLEVILLE, ILLINOIS

0.05 µCAC UCSB Above Ground ESR 1721

09/02/2020





09/02/2020



09/02/2020



09/02/2020



09/02/2020



09/02/2020



09/02/2020



09/02/2020







09/02/2020



09/02/2020



09/02/2020









09/02/2020



