



SIGNIFICANT UNDERMINING OF DOWNSTREAM WING AT ABUT. 2