

DOWNSTREAM LOWER CHORD LOCAL FAILURE  
WITH LAG BOLTED ANGLE REPAIR

2-3/8"

FRACTURE OF INSIDE BEAM

