




LAID-UP STONE RETAINING WALL ALONG LEFT
EMBANKMENT BEYOND ABOUT 2 IS QUITE
UNSTABLE