

RUST HOLES STARTING TO FORM THROUGH FASCIA STRINGER

