



BRIDGE
INSPECTION
AHEAD

STOP

BRIDGE
AHEAD

9-6









BRIDGE
INSPECTION
AHEAD

STOP

9-6

PARALLEL
PARKING
ONLY

NO
PARKING
HERE TO
PROTECT
THE TREE





























SHEAR FAILURE OF TENON AT TOP POST

THE POST HAS PUSHED TOWARDS
MIDSPAN IN REACTION OF THE
THRUST OF DIAG. BRACE

TOP CHORD

POST


TIE BEAM

SHIPKNEE

MIDSPAN

BRACE

NOTE: ALL CHECK BRACES AND MAIN BRACES
ARE SECURE AND IN PLACE







REPAIR TO OUTER ARCH "RIB"
ALONG DOWNSTREAM SIDE
BETWEEN POSTS 4 AND 6





TYPICAL TENON FAILURE ALONG WITH MINOR
POST DROP AT INTERFACE WITH UPPER
CHORD





















1

2

3

4

5















NOTE RECENT REMOVAL OF LONGITUDINAL DISTRIBUTION STRINGERS













