







A photograph showing the interior of a wooden roof structure. The roof is supported by a complex network of dark-stained wooden trusses and rafters. A central horizontal tie beam is visible, with a section of it replaced by a lighter-colored wood, indicating a repair. The roof deck is composed of light-colored wooden planks. The text is overlaid in yellow on the left side of the image.

TIE BEAM 2 WAS HIT AND FRACTURED
2X6 SCAB SPLICE AS REPAIR



NOTE VANDALIZED POSTING SIGN

































ROTTING 2X8 BEARING BLOCKS BELOW BOLSTER



