

TOD Program Steps

 Step 9 Program 2 Step Begins 2100

Flash.
 Red Rest
 Spare 5.
 Spare 3.
 Type 0 Dly Enable. . .
 Det Diag Plan. . . . 0

Dimming Enable.
 Alt Veh Extension
 Det Log Enable.
 Spare 4
 Spare 2

	Phase Number											
	1	2	3	4	5	6	7	8	9	10	11	12
Max 2 Enable
Max 3 Enable
Veh Recall
Veh Max Recall	X	.	.	.	X
Ped Recall
Cond Service Inhibit.
Phase Omit
Special Function

Alt Sequence
 A B C D E F

 Step 10 Program 2 Step Begins 2300

Flash. X
 Red Rest
 Spare 5.
 Spare 3.
 Type 0 Dly Enable. . .
 Det Diag Plan. . . . 0

Dimming Enable.
 Alt Veh Extension
 Det Log Enable.
 Spare 4
 Spare 2

	Phase Number											
	1	2	3	4	5	6	7	8	9	10	11	12
Max 2 Enable
Max 3 Enable
Veh Recall
Veh Max Recall	X	.	.	.	X
Ped Recall
Cond Service Inhibit.
Phase Omit
Special Function

Alt Sequence
 A B C D E F
