

TOD Program Steps

Step 10 Program 2 Step Begins 0000

Flash.	X	Dimming Enable.	
Red Rest	Alt Veh Extension	
Spare 5.	Det Log Enable.	
Spare 3.	Spare 4	
Type 0 Dly Enable.	Spare 2	
Det Diag Plan.	0		

	Phase Number											
	1	2	3	4	5	6	7	8	9	10	11	12
Max 2 Enable
Max 3 Enable
Veh Recall
Veh Max Recall
Ped Recall
Cond Service Inhibit.
Phase Omit
Special Function

	A	B	C	D	E	F
Alt Sequence
