



INADEQUATE BEAM SPACING ALONG CENTERLINE
DOES NOT ALLOW FOR LEGAL LOAD CARRYING
CAPACITY IF WHEEL LOAD DRIFTS OF RUNNERS