

Trees and debris need to be removed from inlet
end of culvert.

