

Extensive corrosion with preforations 2" or larger.

