

FULL DEPTH HOLE BEAM BAY 3 AT ABUT. 1
REBAR HAS MINIMAL SECTION LOSS BUT CONCRETE
HAS DISINTEGRATED

