



APPROX. 2" OF SEPARATION ALONG LOWER
CHORD PLANKS ON RIGHT AT ABUT. 1

LESS THAN 1/3 OF OUTER PLANK IS IN BEARING