



LIMITED BEARING SUPPORT FOR
BOTTOM CHORD OF TRUSS ON
LEFT AT ABOUT 2