

REPAIRS TO UPPER INSIDE CHORD ALONG WITH NEW
LATTICE AND TRUNNELS NEAR ABOUT. 1

