



crack inside brace at 8th vertical left side