

TIE BEAM 2 WAS HIT AND FRACTURED
2X6 SCAB SPLICE AS REPAIR

