



DESCRIPTION BLOCK

Bridge <mark>14</mark>: Slab - 1940 Structure No. 300259001403121 Length: 8' Width: 33.7' Under Clearance: 5.0' Facility Carried: VT122 Bridge Type: CONCRETE SLAB Features Intersected: BROOK Surface: Bituminous Maintenance: State Bridge <mark>15</mark>: Tee Beam - 1928 Structure No. 200259001503122 Length: 44' Width: 23.8' Facility Carried: VT 00122 ML Bridge Type: CONCRETE T-BEAM Features Intersected: MILLER RUN Surface: Bituminous Maintenance/Ownership: State

Bridge 16:
Frame - 1949
Structure No. 300259001603121
Length: 18'
Width: 34.8'
Under Clearance: 5.0'
Facility Carried: VT122
Bridge Type: CONCRETE FRAME
Features Intersected: SQUARE BROOK
Surface: Bituminous
Maintenance: State

Slab - 1974
Structure No. 200259001703122
Length: 35'
Width: 34.5'
Facility Carried: VT 00122 ML
Bridge Type: PRESTRESS CONC SLAB
Features Intersected: MILLER RUN
Surface: Bituminous
Maintenance/Ownership: State
Culvert 18:

Structure No. 300259001803121 Length: 11' Under Clearance: 7.0' Facility Carried: VT122 Bridge Type: CGMPPA Features Intersected: BROOK Maintenance: State

Culvert 19:
Culvert - 1958
Structure No. 300259001903121
Length: 11'
Under Clearance: 6.0'
Facility Carried: VT122
Bridge Type: CGMPPA
Features Intersected: BROOK
Maintenance: State

Culvert 20:
Culvert - 1958
Structure No. 300259002003121
Length: 11'
Under Clearance: 6.0'
Facility Carried: VT122
Bridge Type: CGMPPA
Features Intersected: BROOK
Maintenance: State