Speed Zone

AADT Counts

Crash Locations 2010

2008

Route Log Progress Chart

2200

2200

2200

2200


2200

Please Note: Errors and Omissions May Exist. Contact the VTrans Mapping Unit with questions or concerns.


DRAFT

DISTRICT ROUTE TOWN UNDERHILL Maj-0233

930



DESCRIPTION BLOCK



Bridge 9: Box beam or girders - multiple - 2001 Structure No. 200233000904152 Length: 60' Width: 26.8' Facility Carried: TR 01 FAS 233 Bridge Type: PS/PT CONC BOX BEAM Features Intersected: BROWNS RIVER Surface: Bituminous Maintenance/Ownership: Town
Bridge 8: Stringer/multi-beam or girder - 1957 Structure No. 200233000804152 Length: 74' Width: 31.3' Facility Carried: TR 01 FAS 233 Bridge Type: ROLLED BEAM

Features Intersected: BROWNS RIVER Surface: Bituminous Maintenance/Ownership: Town Bridge <mark>7</mark>: Tee Beam - 1927 Structure No. 200233000704152 Length: 28' Width: 20.9' Facility Carried: TR 01 FAS 233 Bridge Type: CONCRETE T-BEAM Features Intersected: SEYMOUR RIVER

Surface: Bituminous

Maintenance/Ownership: Town

Maintenance/Ownership: Town

Bridge <mark>6</mark>: Slab - 1992 Structure No. 200233000604152 Length: 24' Width: 27.2' Facility Carried: TR 01 FAS 233
Bridge Type: CONCRETE SLAB Features Intersected: SEYMOUR BROOK Surface: Bituminous

980

970

1000

1100

3400

3500

3500