



DESCRIPTION BLOCK

Culvert 229:
Culvert - 1949
Structure No. 300029022910131
Length: 12'
Under Clearance: 8.0'
Facility Carried: VT100
Bridge Type: CONCRETE BOX
Features Intersected: BROOK
Maintenance: State
Culvert 230:

Culvert - 1932
Structure No. 300029023010131
Length: 12'
Under Clearance: 5.0'
Facility Carried: VT100
Bridge Type: CONC BOX WIDE w/SLAB
Features Intersected: BROOK
Surface: Bituminous
Maintenance: State

Bridge 234:
Tee Beam - 1929
Structure No. 200029023410132
Length: 43'
Width: 30.6'
Facility Carried: VT 00100 ML
Bridge Type: CONCRETE T-BEAM
Features Intersected: EAST BRANCH
Surface: Bituminous
Maintenance/Ownership: State

Bridge 236:
Tee Beam - 1929
Structure No. 200029023610132
Length: 34'
Width: 31.7'
Facility Carried: VT 00100 ML
Bridge Type: CONCRETE T-BEAM
Features Intersected: EAST BRANCH
Surface: Bituminous
Maintenance/Ownership: State

Culvert 237:
Culvert - 1948
Structure No. 300029023710131
Length: 25'
Under Clearance: 6.0'
Facility Carried: VT100
Bridge Type: (3) ACCGMP
Features Intersected: BROOK
Maintenance: State

Culvert 238:
Culvert - 1941
Structure No. 300029023810131
Length: 10'
Under Clearance: 5.0'
Facility Carried: VT100
Bridge Type: CONCRETE BOX
Features Intersected: BROOK
Surface: Bituminous
Maintenance: State

Bridge 239:
Stringer/multi-beam or girder - 1941
Structure No. 200029023910132
Length: 49'
Width: 32.1'
Facility Carried: VT 00100 ML
Bridge Type: ROLLED BEAM
Features Intersected: LECLAIR BROOK
Surface: Bituminous
Maintenance/Ownership: State