Route Log and Progress Chart

DISTRICT TOWN DRAFT Please Note: Errors and Omissions May Exist.

ROUTE LINCOLN Maj-0188

STRUCTURE DESCRIPTIONS

Stringer/multi-beam or girder - 1940 Structure No. 200188001501102

Facility Carried: TR 01 FAS 188

Maintenance/Ownership: Town

Maintenance/Ownership: Town

Bridge 17:
Box beam or girders - multiple - 1929
Structure No. 200188001701102

Facility Carried: TR 01 FAS 188 Bridge Type: PRESTRESSED BOX BM

Features Intersected: NEW HAVEN RIVER

Bridge 19: Box beam or girders - multiple - 2015 Structure No. 200188001901102

Facility Carried: TR 01 FAS 188
Bridge Type: PRESTRESSED BOX BEAM

Features Intersected: NEW HAVEN RIVER

Features Intersected: BEAVER MEADOW BROOK

Bridge Type: STEEL BEAM

Surface: Bituminous

Length: 64' Width: 21.5'


Length: 128'

Length: 74' Width: 22.0'

Surface: Bituminous

Maintenance/Ownership: Town





Historic Projects	Functional Class	Curves	Road Widths	AADT	Mileage by Functional Class By Sheet	Mileage by Town By Sheet					
Unknown Bituminous Concrete Surface Treated	1 - Interstate 3 - Principal 5 - Major System Arterial Collector	(degrees) Left	← (ft)	(count)	0188 5 - Major Collector	7.270 LINCOLN - S01880110	7.27 of 7.27	DISTRICT	TOWN	Date: 11/10/16	ROUTE
Retreatment Bituminous Macadam Gravel	2 - Other 4 - Minor 6 - Minor	─ ■■■ ─ Right									
Resurrace Cold Plane and Reclaimed Base and Reclaimed Base and	Freeways and Arterial Collector Expressways	Grades	Traffic Counters	Crash Locations						4 64	Maj-0188
Skinny Mix Concrete Bituminous Concrete	Speed Zones	grade up	ρ	Fatal Property Damage Only				_	LINCOLN	1 of 1	ETE mileage:
Bituminous Seal Gravel	SPEED	(percent) grade down	(counter ID)	☐ Injury ☐ Unknown Crash Type				5	LINCOLN	TWN mileage:	1.1 to 8.37
Indicated plans available - http://vtransmap01.aot.state.vt.us/rp/dpr/Dlwebstore/	25 30 35 40 45 50 55 60 65				Page Total M	leage: 7.270 mi	Page Total Mileage: 7.27 mi			0.0 to 7.27	