



DISTRICT	TOWN	ROUTE
2	GUILFORD	US-5



STRUCTURE DESCRIPTIONS

Bridge 1:
Tee Beam - 1939
Structure No. 200113000113072
Length: 39'
Width: 30.0'
Facility Carried: US 05 ML
Structure Type: CONCRETE T-BEAM
Features Intersected: FALL RIVER
Surface: Bituminous
Maintenance/Ownership: State

Bridge 5:
Stringer/multi-beam or girder - 2017
Structure No. 200113000513072
Length: 89'
Width: 35.5'
Facility Carried: US 05 ML
Structure Type: WELDED PLATE GIRDER
Features Intersected: BROAD BROOK
Surface: Bituminous
Maintenance/Ownership: State

Road Widths	Travellane: 26, 27, 22, 26, 22, 24, 29 Roadway: 27, 22, 26, 22, 24, 29 Lane Count: 2, 2, 2, 2, 2, 2, 2 Base: 26, 27, 22, 26, 22, 24, 29 Subbase: 26, 27, 22, 26, 22, 24, 29
Curves	5, 7, 7, 3, 5, 14, 3, 8, 3, 4, 7, 3, 5, 18, 6, 10, 7, 12, 8, 9, 10, 7, 4, 8, 9, 3, 6, 18, 3, 5, 9, 3, 18, 8, 4, 5
Grades	-5.7, -5.6, -5.4
Guardrails	4, 4
Rumblestrips	2011: STP 2702(1), 1993: STP 9318(1)S, 1983: RS 0113(2)D, 1977: Unknown, 1970: Unknown, 1958: I 91-1(5), 1926: FAP 57-C
Historic Projects	1921: FAP 25, 1939: FAP 25-C, 1924: FAP 57-A, 1926: FAP 57-D
Maintenance Garage	District 2 - HWY Maintenance Dummerston Garage
Speed Zone	40, 35
Functional Class	5
National Highway System	
Limited Access Highway	
Customer Service Level	Local Connector
Traffic Counters	X045
AADT Counts	2018: 900, 2900, 2900, 5700 2017: 910, 2900, 2900, 5700 2016: 910, 2800, 2800, 5600 2015: 920, 2800, 2800, 5600 2014: 910, 2700, 2700, 5600
Crash Locations	HCL Section No. 57

For More Information Contact - Vermont Agency of Transportation, Policy, Planning and Intermodal Development Division - Mapping Section, 1 National Life Drive, Montpelier, VT 05633-5001 Telephone: 802-828-2600.