



REVISIONS AND CORRECTIONS  
 DEC. 6, 1971 - ORIGINAL APPROVAL DATE.  
 JULY 24, 1975 - GRANULAR MATERIAL AT CULVERT LOCATIONS CORRECTED.  
 OCT. 30, 1985 - REVISED TO CONFORM TO 1986 SPECIFICATIONS.  
 JUNE 1, 1994 - REISSUED, WITHOUT CHANGE, UNDER NEW SIGNATURES.  
 AUG 13, 2007 - MINOR CORRECTIONS & REVISIONS DELETED EXTERIOR SERVICE BOX AND CURB STOP, MOVED UNDERDRAIN RISER TO STD D-30.

APPROVED  
*Kenn A. Maschio*  
 ROADWAY, TRAFFIC & SAFETY ENGINEER  
*Rudolf J. Fournier*  
 DIRECTOR OF PROGRAM DEVELOPMENT  
*Mark B. Kuttler*  
 FEDERAL HIGHWAY ADMINISTRATION

CORRUGATED PIPE END SECTION, ARCH END SECTION, AND ELBOW  
 GRANULAR MATERIAL AT METAL CULVERT LOCATIONS  
 TYPICAL WATERFALL FOR CULVERTS

VERMONT AGENCY OF TRANSPORTATION  
 STANDARD  
 D-4