

Fence Summary Hartford-Sharon-Royalton AC IM IR 089-1(8)																
Northbound																
MM to MM	Location	201.11 Clearing & Grub	620.11 4FT CL	620.12 6ft CL	620.16 Gate for 6 ft CL	620.20 Brac for 4ft CL	620.21 Brac for 6ft CL	620.25 W W F w/S P	620.25 W W F (MOD)	620.30 Gate for W W F	620.40 Brac for W W F	620.55 Rem of Fence	620.55 Rem of fence (MOD)	620.60 Barbed Wire Fence	Field measured by	Date
14.64	LT			53			2								TJQ	10/16/2001
14.68	LT			60			2								TJQ	08/08/2001
14.72	RT			200			2						200		TJQ	08/08/2001
14.72 to 15.03	RT	0.157						1513				1513			TJQ	07/25/2001
15.02	RT			186			5						60		TJQ	08/08/2001
15.03 to 15.07	RT	0.021		186			3						186		TJQ	08/08/2001
15.10 TO 15.12	RT							282			4	282			PKP	12/17/2002
15.55 to 15.73	RT	0.090		1020			10				1		1020		TJQ	08/22/2001
16.25 to 16.77	RT	0.242							2637				2637		TJQ	08/22/2001
16.77 to 16.96	RT	0.089							1022				1022		TJQ	09/06/2001
16.94 to 17.23	RT	0.152							1684		2		1684		TJQ	09/06/2001
17.50	RT	0.037		407			8						407		TJQ	10/31/2001
17.55 to 17.85	RT	0.136						1485					1485		TJQ	09/18/2001
17.85 to 18.10	RT	0.130						1414					1414		TJQ	09/19/2001
18.10 to 18.30	RT	0.095		1039			18						1039		TJQ	10/16/2001
18.30 to 18.90	RT	0.342		3726			43					3726			TJQ	10/31/2001
18.90 to 19.93	RT	0.482						5246			2		5246		TJQ	09/19/2001
19.93 to 21.96	RT	0.625													TJQ	10/31/2001
20.60 to 20.75	RT							887			4	681			PKP	12/17/2002
20.88 to 20.95	RT							372			2		372		PKP	12/04/2002
21.00 to 21.05	RT							123					123		PKP	12/04/2002
21.09 to 21.10	RT							50					50		PKP	12/04/2002
21.22 to 21.55	RT	0.154		1681			50					1515			TJQ	10/23/2002
21.53 to 21.78	RT							1176					1344		PKP	12/17/2002
21.82 to 21.89	RT								353				353		PKP	12/17/2002
21.82 to 21.91	RT	0.013		280			16						138		TJQ	09/25/2002
21.91 to 21.96	RT							594			2	594			PKP	12/17/2002
NB total		8.722	619	33715			582	44497	8853		39	31963	55701			

3