

Fence Summary Hartford-Sharon-Royalton AC IM IR 089-1(8)																
MM to MM	Location	201.11 Clearing & Grub	620.11 4FT CL	620.12 6ft CL	620.16 Gate for 6 ft CL	620.20 Brac for 4ft CL	620.21 Brac for 6ft CL	620.25 W W F w/S P	620.25 W W F (MOD)	620.30 Gate for W W F	620.40 Brac for W W F	620.55 Rem of Fence	620.55 Rem of fence (MOD)	620.60 Barbed Wire Fence	Field measured by	Date
Southbound																
0.05 to 0.25	LT	0.116													WRS	11/28/2001
0.06	LT			270			12						270		PKP	12/04/2002
Int 10 Ramp C 20+00 to SB 1.05	LT	0.129		1887			26						1887		TJQ	11/20/2002
1.05 to 1.62	LT	0.230													WRS	11/28/2001
1.09 to 1.30	LT			1096			18					1096				
1.30 to 1.56	LT			1498			24					1498			TJQ	09/11/2002
2.30 to 2.55	LT	0.133		1205			28					1205			TJQ	09/11/2002
2.99 to 3.27	LT			1169			24	242				1411			TJQ	09/11/2002
3.00 to Exit 1 Ramp C 9+00+/-	LT	0.388													WRS	11/28/2001
3.27 to Exit 1 Ramp C 6+50+/-	LT			2662			44	274				2936			TJQ	07/31/2002
3.27 TH #46	LT			279			14						180		TJQ	06/05/2002
3.44 to 3.52	LT							472					472		PKP	12/04/2002
3.94 to 4.21	LT	0.131		1409			24						1409		TJQ	07/17/2002
4.21 to 4.23	LT	0.029							627				876		PKP	12/17/2002
4.27 to 4.30	LT	0.029		129			9					45			TJQ	08/28/2002
4.57 to 4.65	LT	0.039		393			5						393		PKP	12/04/2002
4.64 to 4.75	LT								593				593		PKP	12/04/2002
4.83 to 4.86	LT	0.015							105				105		PKP	12/04/2005
4.91 to 4.93	LT	0.010													TJQ	05/22/2002
5.60 to 5.63	LT							139					139		PKP	12/04/2002
5.70 to 5.75	LT	0.030						284					284		PKP	12/04/2002
5.98 to 6.02	LT	0.019						136					136		PKP	12/04/2002
6.12 to 6.13	LT	0.005						154					154		PKP	12/04/2002
6.21 to 6.22	LT							36					36		PKP	12/04/2002
6.21 to 6.27	LT	0.030													TJQ	05/22/2002
6.27 to 6.31	LT	0.019						290					290		PKP	12/04/2002
6.51 to 6.60	LT	0.044		451			14						451		TJQ	07/17/2002
6.93 Bridge #11	LT			73			2						73		PKP	12/04/2002