



KEY:
 DELAMINATED AREAS
 SPALLED AREAS

- NOTES:
 1. ONLY PIERS WITH DEFICIENCIES NOTED DURING THE INSPECTION ARE SHOWN.
 2. SEE SHEET 22 FOR SUBSTRUCTURE CONCRETE REPAIR DETAILS.

VANASSE HANGEN BRUSTLIN, INC.

STATE OF VERMONT AGENCY OF TRANSPORTATION			
Town Of HARTFORD		Bridge No. 11S	
Highway No. I-89 SB		Log Sta.	
		Surv. Sta.	
I-89 SB OVER WHITE RIVER, VT 14 & NECR			
PIER 1 REPAIR AREAS			
Designed By T.S. BRYANT		Drawn By B.J. MASSE	
Checked By S.M. HODGDON	Date 9/98	Bridge Design Supervisor C.D. BAKER	Date 9/98
PROJECT HARTFORD		PROJECT NO. IR 089-1(13)	
VHB Cad Filename 50699P1		Bridge Sheet No. 34	
		Sheet 34 of 101	