



See also  
woodford FAP 105-J  
Pin 99R813  
# woodford F 105-R  
Pin 99R818

Existing Pavement Removal  
91+50 - 92+25, Item 101-A  
89+00 - 92+00, Item 122  
96+00 - 101+00, Item 122  
100+50 - 101+50, Item 118-A  
103+50 - 105+00, Item 118-A

PARCEL:	3	ALMA E. CHAMPINE
GRANTOR:	102+00	102+03
TAKING:	1	1
REMAINER:	NONE	
RIGHTS:	NONE	
TITLE TAKEN:	COND.	
RECORDED:	WOODFORD - BK 21 - PG 459 - 121	Per FF

Rev Curve Data  
Δ 9°54'30" RHY  
D 257'  
C 2864.77'  
L 248.33'  
E 475.41'  
T 10.71'Bank 3' Per Ft

104+22 Rt. Precast Reinf. Conc. Pipe Drop Inlet Item 537 E  
STA. 102+60 (102+10 RT - 104+22 LT)  
NEW 36" x 240" SEAMLESS CURVED WATER TUBE ITEM 538 UNDER ROADWAY  
NEW 180" SLEEVE FOR WATER PIPE ITEM 431 UNDER ROADWAY  
EXCAVATION TO BE PAID FOR TRENCH EXCAVATION ITEM 103