



**RFI**

DATE: 10/19/07  
RFI #: NCR-04

**FROM:** John Bettin  
DS Brown Co  
300 East Cherry Street  
North Baltimore, Ohio 45872  
[jbettin@dsbrown.com](mailto:jbettin@dsbrown.com)

**TO:** Andy White  
CCS Constructors  
138 Munson Ave  
Morrisville, VT 05661  
[awhite@contractorscranesvc.com](mailto:awhite@contractorscranesvc.com)

**Direct Dial:** 952-693-1099  
**FAX:** 419-257-0332

**PHONE:**  
**FAX:**

**REFERENCE:** New Haven-Weybridge  
Non-Conformance to Post Base Plate

**DSB JOB #:** 20388-1206

**INFORMATION REQUESTED:**

**Ref. Attached sketch SK-NC04-01 & DSB shop drawing sheet 01**  
A mistake was made to the length of the 1/4" thick anchor plates 1a1 on assembly 1B shown on DSB shop drawing sheet 01. The length of these plates were inadvertently changed in BOM after the initial approval and we fabricated them to 1'-3" in lieu of the 1'-4" shown on the detail. Since the rods and holes were dimensionally worked off the center of the plate, unfortunately this error was not discovered until after they were fabricated and set to ship. Since the timing of this project has become critical we are asking for acceptance of the anchors as shown on attached sketch SK-NC04-01.

Please call if you have any questions.

- Thank You

**REPLY:**

---

---

**FROM:**

---

---

Approved  
CPW  
10/19/07

070-BR

The D.S. Brown Company  
300 E. Cherry Street  
North Baltimore, Ohio 45872  
419.257.3561  
Fax: 419.257.2200  
Engineering Fax: 419.257.0332  
E-mail: [dsb@dsbrown.com](mailto:dsb@dsbrown.com)  
[www.dsbrown.com](http://www.dsbrown.com)

Chaska Operations  
4201 Norex Drive  
Chaska, Minnesota 55318  
952.368.3000  
Fax: 952.448.7000

International Division  
7 Temasek Boulevard  
#16-03 Suntec Tower One  
Singapore 038987  
+65.333.0911  
Fax: +65.333.0922  
E-mail: [dsbrown@mbx2.singnet.com.sg](mailto:dsbrown@mbx2.singnet.com.sg)