

CON-SERV INC
STANDARD OPERATING PROCEDURE

S.O.P. No 1011 **EFFECTIVE DATE:** January 1, 1979
DESCRIPTION: Manufacturing steps for **Q.C. APPRVD.:** *RR*
 fabrication of typical **SHT. 2 OF 2**
 slide bearings. **REVISED DATE:** October 28, 1996

STEP	PROCEDURE	COMMENTS
9.	Remove the plates from the press and trim the excess tape from the edges.	
10.	Clean TFE with solvent.	
11.	Check the job quantities and mark items as required.	
12.	Package with tape surfaces together.	

RECEIVED
 DEC 15 2006
 BY _____ DATE 01-05-07
 055 SS