



WEIGHT  
LIMIT  
8  
TONS




















CENTERLINE SIDEWALK STRINGER OVER FIRST BRACKET  
FROM ABUTMENT 2 HAS CRUSHED AND DROPPED AWAY  
FROM SLAB APPROX. 1"





SIDEWALK STRINGER









CHORD RUSTED THRU



75% OF BOTTOM CHORD RUSTED THROUGH  
AT PANEL POINT 4 (OUTSIDE CHANNEL AND  
SPlice PLATE RUSTED COMPLETELY THROUGH)







































