



NO FURTHER ROOM FOR
ANY LONGITUDINAL MOVEMENT
AT ANY OF THE HINGE JOINTS

NOTE: IMPACTING RUNNER
AND BRIDGE RAIL POST