



NO THRU TRAFFIC

CHEVROLET



















1-1/8" OF TRANSLATION IN ONE FOOT AT RIGHT END
OF ABUTMENT 1



INADEQUATE BEAM SPACING ALONG CENTERLINE
DOES NOT ALLOW FOR LEGAL LOAD CARRYING
CAPACITY IF WHEEL LOAD DRIFTS OF RUNNERS





