

HEAVY SECTION LOSS ALONG STRINGER 2 IN
FLOORBEAM BAY 4

